

**From:** [Tossi, Lisa](#)  
**To:** [Blathras, Constantine](#)  
**Cc:** [Reed, Michael](#)  
**Subject:** Meyer Steel Drum, ID 031600APY  
**Attachments:** [DRF Stack Test.pdf](#)

---

Dino,

Attached is the stack test report that we had discussed during our call on January 27<sup>th</sup>. Also, the source is going to submit a revised Best Management Practices Plan to reflect exhaust and ducting of the drum top cutter area to the drum furnace. We have resolved the drum top cutter (and cleaning) area issue.

Thanks,

Lisa

**Lisa Tossi**

Title V Permit Engineer, Bureau of Air  
Illinois Environmental Protection Agency  
1021 N. Grand Avenue East  
Springfield, IL 62794  
Phone: 217-782-7272/Fax: 217-524-5023  
[Lisa.Tossi@illinois.gov](mailto:Lisa.Tossi@illinois.gov)